

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



All shingle ridges lost in one day! What a waste of money!

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



1960's sea wall now exposed with 19 courses (yesterday there were 9 courses exposed) and more shingle lost from the embankment!

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



Embankment just crumbling away – 1 hour yet to go for high tide!

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



10 new courses exposed today!

Jury's Gap - 1.10.08 - 1 hour before high tide 12.21 pm - Loss of shingle and exposure of structures within 24 hours!



Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



Evidence of sandy material rather than correct shingle quality

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



MOD Lookout – all shingle ridges gone – base of structure totally exposed

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



Concrete posts and rock gabions clearly visible

Jury's Gap – 1.10.08 – 1 hour before high tide 12.21 pm – Loss of shingle and exposure of structures within 24 hours!



Total loss of access around the MOD Lookout!